

Conversion table C_p to C_9

| C_p | C_9 |
|-----------|-------|
| 0.0 - 0.1 | 0 |
| 0.2 - 0.3 | 1 |
| 0.4 - 0.5 | 2 |
| 0.6 - 0.7 | 3 |
| 0.8 - 0.9 | 4 |
| 1.0 - 1.1 | 5 |
| 1.2 - 1.4 | 6 |
| 1.5 - 1.8 | 7 |
| 1.9 | 8 |
| 2.0 - 2.5 | 9 |